THE CALIFORNIA STATE UNIVERSITY ANNUAL REPORT OF EXEMPTIONS FROM THE BIDDING PROCESS DUE TO UNEXPECTED CAUSES January 1, 2015 through December 31, 2015

| CAMPUS | CONTRACTOR | CONTRACT# | DATE | AMOUNT | EMERGENCY EVENT |
|------------------|---------------------------|------------|-----------|---------------|---|
| Bakersfield | None | | | | |
| Channel Islands | None | | | | |
| Chico | None | | | | |
| Dominguez Hills | None | | | | |
| East Bay | None | | | | |
| Fresno | West Pacific Electric Co. | 74396 | 4/13/2015 | \$ 19,487.00 | line regulator rusted and snapped off, causing extensive flooding and electrical equipment damage. |
| | Strategic Mechanical | 74475 | 5/11/2015 | \$ 14,589.42 | Major leak in hot water line between North (#13) and South (#14) Gyms caused a system shutdown with no heat or water to the buildings. Flange on underground pipe rusted and when hot water line was pressured up, it caused water seepage. |
| | Strategic Mechanical | 74886 | 6/25/2015 | \$ 12,052.73 | Intrastructure project. Installed new electric not water neater and HVAC unit. |
| | Pistacchio Pump Co. | 75453 | 8/19/2015 | \$ 39,592.14 | Repair pump to Well #2, one of campus' main water wells due to excessive sand, silt and dirt. Repaired pump and converted to variable frequency drive including electric hardware and plumping. |
| | Ardent General, Inc. | 76123 | 9/14/2015 | \$ 14,862.27 | Repairs to Post Harvest Building (#226) damaged by car missing roundabout and driving into corner of the building. Damage included structural, gas and electrical lines. Repairs included demolition, concrete, plumbing, carpentry and painting. |
| | Outback Concrete | 76588 | 11/5/2015 | \$ 14,720.00 | Concrete sidewalk demolition and repairs in Quad area at Social Science (#10), McKee Fisk (9), Family Food Science (#8) and Public Health (#7) buildings due to fall and injury caused by uneven sidewalk. |
| Fullerton | None | | | | |
| Humboldt | None | | | | |
| Los Angeles | None | | | | |
| Long Beach | ABM | 46795 | 3/1/2015 | \$ 5,000.00 | emergency repair. |
| | Simplex Grinnel | 47450 | 6/23/2015 | \$ 142,470.99 | Fire alarm panel in Engineering Computer Science Building (#83) malfunctioned, alarm not working properly resulting in a manual fire watch in building 24/7 until fire alarm panel was replaced. |
| | ARB | 48070 | 9/15/2015 | \$ 8,970.00 | Bleacher stuck in upright position at the Walter Pyramid (#73) due to a lack or low level of lubrication causing the bleachers to exhibit a bouncing or unsteady descent and ascent. Bleachers are required to be operational at all events. |
| Maritime Academy | None | | | | |
| Monterey Bay | None | | | | |
| Northridge | None | | | | |
| Pomona | General Pump Company | 0000059720 | 9/16/2015 | \$ 74,000.00 | Water quality from Well #1 degraded to a point where public safety is a concern. Required well head rehabilitation, inspection of well casing and pumping equipment. Well #1 is the campus' only source of groundwater for potable use. The quality of the water distributed to the campus was at risk. There was a potential to affect public safety. Immediate work and remedial measures were required to protect property and/or the public's health, safety and welfare. |
| Sacramento | None | | | | |

3/18/2016 Page 1

THE CALIFORNIA STATE UNIVERSITY ANNUAL REPORT OF EXEMPTIONS FROM THE BIDDING PROCESS DUE TO UNEXPECTED CAUSES

January 1, 2015 through December 31, 2015

| CAMPUS | CONTRACTOR | CONTRACT# | DATE | AMOU | NT | EMERGENCY EVENT |
|---------------------|----------------------------|-----------------|------------|-------------|--|--|
| San Bernardino | | | 27112 | 7 | | Repair vault #12 due to a leak caused by high temperature water line mechanical joint |
| | JCS Welding | SBCMP0000040673 | 1/8/2015 | \$ | 5,418.00 | gasket failure in the high temperature water loop; vault located underground in the |
| | | | | | | middle of the road, northeast corner of the Health Center. |
| | | | | | | Removed and replaced two existing sewage pumps, two existing gray water pumps and |
| | Roto-Rooter | SBCMP0000041725 | 5/15/2015 | \$ 27,495 | 27,495.00 | control boxes due to their age located in Performing Arts Building (#20). Failure to |
| | | | | | | operate will cause backup of sewage and/or gray water in the basement of the Performing Arts Building. |
| | | | | | | Emergency troubleshoot and repair of compressor #4 located in HVAC Central Plant |
| | Pump Engineering | SBCMP0000042218 | 6/29/2015 | \$ 5,740.00 | | (#5) due to wear and tear. Diagnoses determined that the compressor would need |
| | | | | | rebuilding to repair in order to deliver compressed air across campus for the building | |
| | | | | | | controls. |
| San Diego | None | | | | | |
| San Francisco | None | | | | | |
| San José | Clean Harbors | 3000014201 | 3/5/2015 | \$ | 82,704.00 | Removal of contaminated soil from jobsite. Discovered during demolition of BB |
| | | 0000011201 | 0,0,2010 | Ψ | 02,701.00 | Building. |
| San Luis Obispo | None | | | | | |
| San Marcos | None | | | | | |
| Sonoma | | | | | | |
| | Darrale Patrias Electrical | 0000009674 | 7/28/2015 | \$ | 25,826.45 | , |
| Stanislaus | Contractor Inc. | | | | | Room (#15). Included installation of temporary power until more permanent repair could |
| | | | | | | be diagnosed and performed. The work was completed in response to a whole building power failure that affected entire building operations. |
| | Darrale Patrias Electrical | 0000009709 | 8/11/2015 | \$ | 69.295.00 | Provide permanent power restoration to Physical Education Building (#15) with |
| | Contractor Inc. | 0000000.00 | 5, 1.,20.0 | | 00,200.00 | installation of new 300 kV transformer. The work was completed in response to the |
| | | | | | | whole building power failure that had been addressed with temporary power with PO |
| | | | | | | 9674. |
| | Howk Systems | PC51310 | 9/3/2015 | \$ | 9,139.43 | |
| | | | | | | The work was completed in response to the deep well pump failure that provides the |
| | | | | | | campus the only source of non-potable water. The only alternatives to repairing the |
| | | | | | | pump would be to install a new well and pump or to transfer all non-potable water uses to potable water. |
| | Darrale Patrias Electrical | 0000009878 | 11/25/2015 | \$ | 14,395.00 | Repair and replace high voltage breaker at campus main switch due to campuswide |
| | Contractor Inc | | | | , | power outage bringing campus power grid back to optimal operational configuration. |
| | | | | | | The work was in response to the unexpected power failure to the entire campus that |
| | | | | | | was temporarily addressed on November 23, 2015. The temporary fix left the campus |
| | | | | | | at risk of continued power failures with no source for temporary power. |
| Chancellor's Office | None | | | | | |

TOTAL: \$ 585,757.43

Page 2 3/18/2016